

- 2011 - As supplied by LEDA  
2012 - Rebuilt Engine side picking head - New main drive bar  
2013 - Rebuilt Driver side picking head  
2015 Replace front driverside drive hub.  
2015 - Motor side timing chains.  
2015 - Radiator full refurbishment  
2016 → Both main hydraulic pumps serviced.  
→ Bosch Rexroth  
2016 Hydraulic oil full replacement + all filters  
2016 Driver side timing chains  
2017 Driver Side floor + floor belt  
2017 Augers in place of belts at bucket conveyors  
Drivers side

2018 New floor far side of driver + belt  
new sensor arms  
Auger upgrade non drivers side

2014 - ~~New~~ front windscreens .  
New split screen monitor  
Every year oil + filter change on engine  
hydraulic filters changed.

both bucket belts - 2014 + 2017

Long side belts - Driverside 2017  
Engine side 2016

Cross conveyor belt 2016